

# General Environmental Incident Summary

**Incident:** 94      **Date/Time Notice:** 6/10/1989      **DEM Incident No:**

**Responsible Party:** Bismarck Airport Authority

**Date Incident:** 6/10/1989      **Time Incident:**      **Duration:**

**County:** Burleigh      **Twp:** 138      **Rng:** 80      **Sec:** 15      **Qtr:** NE

**Lat:** 46.77291      **Long:** -100.76300      **Method:** Derived from TRS

**Location Description:** Airport tank farm

**Submitted By:**

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:** Rod Beck

**Contact Person:** Kevin Christ  
Airport Road  
Bismarck, ND 58504

**Distance Nearest Occupied Building:**

**Type of Incident:** HYDROCARBON

**Description of Released Contaminant:** Jet A Fuel

**Volume Spilled:** 100.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:**

**Reported to NRC:** No

**Cause of Incident:**

FUEL HAULER TRIED TO FILL A FULL TANK CAUSING OVERFILL SPILL. CONTAINED ON SITE.  
WILL PICKUP CONTAMINATED SOILS AND WILL FARM THEM ON AIRPORT PROPERTY.

**Risk Evaluation:**

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

**Wastes Disposal Location:**

**Agencies Involved:**

